CCR LANDFILL NAME: Plant Crist Ash Landfill 1	
OWNER OF CCR LANDFILL: Gulf Power Company	
INSPECTION DATE: November 13, 2018	
INSPECTING ENGINEER: James C. Pegues, P.E. FL PE 52519	
APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT	3,960,650
THE TIME OF INSPECTION (CU. YDS.)	
ANY CHANGES IN GEOMETRY OF THE CCR UNIT SINCE THE	NO
PREVIOUS ANNUAL INSPECTION?	
(IF YES, DESCRIBE):	
ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL	
WEAKNESS OF THE CCR UNIT, OR ANY EXISTING CONDITIONS	
THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT	NO
THE OPERATION AND SAFETY OF THE CCR UNIT OR	
APPURTENANT STRUCTURES?	
(IF YES, DESCRIBE):	
ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE	
STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL	NO
INSPECTION?	
(IF YES, DESCRIBE):	
NATIONAL CORRECTIVE ACTIONS IDENTIFIED BURNING THE	
WERE ALL CORRECTIVE ACTIONS IDENTIFIED DURING THE	N/A
PREVIOUS ANNUAL INSPECTION COMPLETED? (IF NO, DESCRIBE): There were no corrective actions identified in the p	mandana Amminal Imair

Based on the results of my inspection and review of the data provided, it is my professional opinion that the report has been completed in accordance with 40 CFR 257.84(b).

James C. Pegues, K.E. Date

