257.83 (b)(2)	REPORT OF ANNUAL INSPECTION OF CCR SURFACE IMPOUNDMENT					
	FACILITY NAME: Plant Smith – Ash Pond					
	OWNER/OPERATOR OF FACILITY: Gulf Power					
	INSPECTION DATE: November 20, 2019					
	INSPECTING ENGINEER: Kevin S. Brown, P.E. (FL PE# 57819)					
	Based on the results of my inspection and review of the data provided, it is my professional					
	opinion that the report has been completed in accordance with 40 CFR 257.83(b).					
(i)	ANY CHANGES IN GEOMETRY OF THE IMPOUNDING			NO		
	STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION?					
(ii)	LOCATION AND TYPE OF EXISTING INSTRUMENTATION NO IN				INSTRUMENTATION	
(ii)	MAXIMUM RECORDED READING OF EACH INSTRUMENT			N/A		
	SINCE PREVIOUS ANNUAL INSPECTION					
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE					
	IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION*					
	MIN. DEPTH: 3 ft	MAX. DEPTH: 10 ft	PRESENT	NT DEPTH: 9.5 ft. (at deepest		
			area)			
	MIN. ELEVATION: 11	MAX. ELEVATION: 16.85	PRESENT	RESENT. ELEVATION: 13.5		
(iii)	APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR					
	SINCE PREVIOUS ANNUAL INSPECTION.**					
	MIN. DEPTH: 0 ft	MAX. DEPTH: 41 ft	PRESENT	PRESENT DEPTH: 41 ft (at deepest		
			area)			
	MIN. ELEVATION: 0 ft	MAX. ELEVATION: 46.0 ft	PRESENT	ENT ELEVATION: up to 46.0 ft		
(iv)	APPROXIMATE STORAGE CAPACITY OF			2,579,480 yd ³ ***		
	IMPOUNDING STRUCTURE AT TIME OF INSPECTION.		2,575,460 yu · · ·			
(v)	APPROXIMATE VOLUME	OF IMPOUNDED WATER	WATER:		CCR : 2,059,861 yd ³	
	AND CCR AT TIME OF INSI	PECTION****	<85,000	yd ³	CCR. 2,039,801 yu	
(vi)	ANY APPEARANCE OF AN ACTUAL OR POTENTIAL					
	STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO			NO		
	ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE					
	THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF					
	THE CCR UNIT AND APPURTENANT STRUCTURES?					
	(IF YES, DESCRIBE):					
(vii)	ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE			NO		
	STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL					
	INSPECTION?					
	(IF YES, DESCRIBE):					

^{*}Water elevation estimated from aerial survey

^{**}Elevation and depth of CCR includes the area where CCR is being actively placed and compacted per the approved closure plan.

^{***}Depths, elevations and storage capacity are estimates derived by qualified personnel from available information and do not include the area above the original CCR elevation where CCR is being placed and compacted per the approved closure plan, e.g., the storage capacity does not include placed and compacted CCR.

^{****} Volume of CCR does not include CCR that is being placed and compacted per the approved closure plan because it is not considered impounded.

Based on the results of my inspection and review of the data provided, it is my professional opinion that the report has been completed in accordance with 40 CFR 257.83(b).

Kevin S. Brown, P.E.

1/29/2020

Date